

- 1) PE faston removed
- 2) Position of power bugs moved by 10.16mm to the bottom. Sequence changed for optimal power distribution.