

- 1) Utility connector (5 x jumper pins, 2.54mm pitch) rotated by 90 degree
- 2) PE fastons removed
- 3) Position of power bugs moved by 10.16mm to the top. Sequence changed for optimal power distribution.
- 4) +5V Stby input changed from power bug to faston, location changed from right side to left (backside view)
- 5) 23000-042: ADC (automatic Daisy Chain / special connector), 23001-012: EDC (Electronic Automatic Daisy Chain / IC)